Leads4Pass

HP2-T26 ^{Q&As}

Servicing HP BladeSystem Solutions

Pass HP HP2-T26 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.leads4pass.com/hp2-t26.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

Which processor type is used with the HP BL460c G6 Server Blade?

A. Dual-Core Intel?Itanium?Processor

B. Intel?Xeon?Processor

C. HP PA-RISC FSB, double data rate

D. AMD Opteron processor

Correct Answer: B

QUESTION 2

The customer replaced a server blade that had been backed up to an Ultrium 448 Tape Drive. How should you restore the server blade and have it fully functional?

A. During POST, you select F9 to restore from tape.

B. You power up the server blade and hold down the One-Button Disaster Recovery (OBDR) button.

C. You insert the tape that has the backup of the server, then power up the blade.

D. You power up the blade and select F9 during POST to enter into the RBSU. In the RBSU, you select Restore from tape

Correct Answer: B

QUESTION 3

Which new technologies are introduced in the new G7 Series c-Class server blades? (Select two)

A. Fully Buffered DIMMs

B. Flex-10 Ethernet support

C. 10Gb Ethernet on-board

D. FlexFabric support

E. Internal MicroSD card slot

Correct Answer: CD

QUESTION 4

After executing a troubleshooting plan, which tools may provide indications of a successful remedy in step 5 of the

6-step HP Troubleshooting Methodology? (Select two.)

A. HP Screwdriver Toolkit

B. Integrated Management Log (IML)

C. MSDN Toolkit

D. MSCOIMFIG

E. OS Event Log

Correct Answer: BE

QUESTION 5

What are some general requirements that must be met to update Virtual Connect firmware? (Select three.)

A. If using Virtual Connect Enterprise Manager (VCEM), the VC domains must be placed in Maintenance Mode, or the firmware updates are blocked.

B. Run only one instance of the Virtual Connect Support Utility (VCSU) to access a single enclosure on a single client at one time.

C. Make sure the VC domains are not in Maintenance Mode, so the firmware updates have direct access.

D. Run multiple instances of the VCSU, with multiple clients, to access an enclosure faster.

E. Do not close the console application when a firmware update is in progress as it may corrupt the firmware.

Correct Answer: ABE

[Latest HP2-T26 Dumps](#)   [HP2-T26 PDF Dumps](#)   [HP2-T26 Practice Test](#)