

HP0-S41^{Q&As}

Building HP Server Solution

Pass HP HP0-S41 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.leads4pass.com/hp0-s41.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers





QUESTION 1

Which HP C70Q0 component is needed to attach a BL460C Gen9 server blade to a third-party VoIP card?

- A. HP Smart Array P244br controller
- B. HP Storage Blade
- C. HP Onboard Administrator
- D. HPPCI ExpansionBlade

Correct Answer: D

QUESTION 2

In a Blade System enclosure, which component allocates power to the device bays based on the specific configuration of each blade?

- A. PCIExpansionBlade
- B. Insight Display
- C. Onboard Administrator
- D. Interconnect Module

Correct Answer: C

QUESTION 3

Which iLO Management Engine feature records configuration changes and helps an HP Support specialist identify the core issues on a ProLiant Gen8 server?

- A. Sea of Sensors
- B. Active Health System
- C. Array Diagnostics Utility
- D. Integrated Management Log

Correct Answer: B

QUESTION 4

Which HP technologies integrate with HP Intelligent Series Racks\\'? (Select two.)

A. HP Intelligent Power Distribution Units (iPDU)



https://www.leads4pass.com/hp0-s41.html

2024 Latest leads4pass HP0-S41 PDF and VCE dumps Download

- B. HP StoreServ inform Console
- C. HP Intelligent Management Center (1MC)
- D. HP Lights-0ut Management (iLO)
- E. HP intelligent Provisioning

Correct Answer: CD

QUESTION 5

You are trying to log in to the Virtual Connect Manager of one of the c7000 enclosures, out the Virtual Connect Manager is disabled. What is a probable reason for this issue?

- A. The stacking link of the Onboard Administrator is disconnected
- B. The enclosure is managed by HR QneView
- C. The Virtual Connect Manager license is not enabled
- D. The Virtual Connect Manager and Onboard Administrator firmware versions are incompatible

Correct Answer: B

HP0-S41 PDF Dumps

HP0-S41 Exam Questions

HP0-S41 Braindumps