

HP2-T23^{Q&As}

Supporting Industry Standard Server Solutions

Pass HP HP2-T23 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.leads4pass.com/hp2-t23.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers





QUESTION 1

What should a support engineer use to perform a firmware update to a BladeSystem PCI Expansion Blade?

- A. HP SmartStart
- B. HP SUM
- C. Firmware Maintenance DVD
- D. Onboard Administrator GUI

Correct Answer: D

QUESTION 2

A customer wants to verify that all the memory DIMMs in a ProLiant Gen8 server are genuine HP. What will provide this information?

- A. Windows Event Viewer
- B. ROM Based Setup Utility (RBSU)
- C. iLO Event Log
- D. SmartMemory

Correct Answer: D

QUESTION 3

You replaced a Smart Array P812 in a ProLiant DL380 G7 storage server. What should you do next?

- A. Check the FBWC charge.
- B. Replace the cache module.
- C. Verify that the firmware level is current.
- D. Install the BBWC battery.

Correct Answer: C

QUESTION 4

A ProLiant DL380 Gen8 ser/er has become unresponsive several times during the last two weeks You contacted HP Technical Support and were asked to send them the Active Health System log for the last two weeks Where can you download this log? [Select two.)



https://www.leads4pass.com/hp2-t23.html

2024 Latest leads4pass HP2-T23 PDF and VCE dumps Download

- A. Array Configuration Utility (ACU)
- B. iLO infoimatioi page
- C. Integrated Management log (IML)
- D. Intelligent Provisioning Maintenance page
- E. ROM Based Setup Utility (RBSU)

Correct Answer: BD

QUESTION 5

After a system administrator replaces a system board on an HP server blade, the BIOS update fails. After it reboots, the server works with the old BIOS version.

What is the next step to troubleshoot this issue?

- A. Use RBSU to clear the NVRAM.
- B. Order a new system board
- C. Use a new Firmware Update CD.
- D. Attempt to reflash the BIOS again.

Correct Answer: D

HP2-T23 VCE Dumps

HP2-T23 Practice Test

HP2-T23 Study Guide