

E20-855^{Q&As}

Networked Storage-SAN Expert for Implementation Engineers

Pass EMC E20-855 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.lead4pass.com/E20-855.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by EMC
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



VCE & PDF Lead4Pass.com

https://www.lead4pass.com/E20-855.html

2023 Latest lead4pass E20-855 PDF and VCE dumps Download

QUESTION 1

Click the Exhibit button. The customer added a new iSCSI server to the MP-1620M. They can not access the storage array on IP address 10.5.19.1. The customer\\'s network is setup for Fast Ethernet. Please see exhibit. What is the issue?

- A. IP address setting is wrong
- B. Port Speed setting is wrong
- C. Port Parameter setting is wrong
- D. Autonegotiations setting is wrong

Correct Answer: A

QUESTION 2

Your customer has three fabric islands. One fabric island has three ED-1032s. Two other fabric islands have two DS16B2s in each. The customer wants to migrate to two fabrics built of two MDS 9509s in each fabric. Several SUN Solaris servers must be migrated on-line to the new fabrics. What are two [2] steps required to perform this migration?

- A. Disable one path to the fabric
- B. Apply the zoning to the new switch
- C. Reactivate the disabled path on the new fabric with PowerPath commands and set the speed to 1GB
- D. Reactivate the disabled path on the new fabric with PowerPath commands and set the speed to 2GB

Correct Answer: AC

QUESTION 3

A Customer is attempting to configure Windows hosts to boot from the SAN. They accessed the SAN volume and successfully installed the OS. When the server reboots it cannot find the operating system. What must be done to allow the server to boot?

- A. Set VCMDB visibility on
- B. Disable SCSI Controller BIOS
- C. Install and configure the SCSIport driver
- D. Install and configure the STORport driver

Correct Answer: B



https://www.lead4pass.com/E20-855.html

2023 Latest lead4pass E20-855 PDF and VCE dumps Download

Your customer recently added a Celerra to their environment and implemented iSCSI on Windows 2003 servers. They created the IQN name for the Windows servers via a script and the name looked as follows: iqn.2003-04.com.emc.HostA.0083 The servers cannot see the iSCSI LUNs. What is the reason for this?

- A. The network portal is not reachable
- B. Celerra converts upper case into lower case and Windows does not
- C. Customer download and installed the latest iSCSI driver from Microsoft\\'s website
- D. Customer download and installed the latest iSCSI driver from the HBA vendor\\'s website

Correct Answer: B

QUESTION 5

A customer has a Solaris host connected to an edge switch in a fabric. Storage is connected to the core. The customer is using Open Trunking on the switches to balance I/O loads across the ISLs. Occasional CSI Transport Errors?are appearing in /var/adm/messages. What is the cause?

- A. Open Trunking is rebalancing the ISLs
- B. Open Trunking is being used in interop mode
- C. Open Trunking is not installed on both switches
- D. Open Trunking requires switches with the same firmware

Correct Answer: A

Latest E20-855 Dumps

E20-855 Practice Test

E20-855 Braindumps

To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product!

100% Guaranteed Success

100% Money Back Guarantee

365 Days Free Update

Instant Download After Purchase

24x7 Customer Support

Average 99.9% Success Rate

More than 800,000 Satisfied Customers Worldwide

Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

https://www.lead4pass.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you. To update a previously submitted ticket:





Any charges made through this site will appear as Global Simulators Limited.

All trademarks are the property of their respective owners.

Copyright © lead4pass, All Rights Reserved.