

HP2-T23^{Q&As}

Supporting Industry Standard Server Solutions

Pass HP HP2-T23 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.leads4pass.com/hp2-t23.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers





QUESTION 1

A customer wants to verify that all the memory DIMMs in a ProLiant Gen8 server are genuine HP. What will provide this information?

- A. Windows Event Viewer
- B. ROM Based Setup Utility (RBSU]
- C. iLO Event Log
- D. SmartMemory

Correct Answer: D

QUESTION 2

Which statements are correct about the HP Customer Self Repair (CSR) program?

- A. A travel and labor charge applies when customers request HP to replace parts.
- B. A travel and labor charge does not apply when customers decline to replace a mandatory CSR part.
- C. A travel and labor charge does not apply when customers decline to replace an optional CSR part.
- D. A travel and labor charge applies when customers decline to replace an optional CSR part.

Correct Answer: A

QUESTION 3

Which components are integrated into the HP Service Pack for ProLiant (SPP)? (Select three)

- A. HP Advanced Diagnostic Utility
- B. HP Smart Update Firmware DVD
- C. HP Advanced Configuration Utility
- D. HP ProLiant Support Packs
- E. HP Smart Update Manager
- F. HP ProLiant Version Control DvD 24 of 60

Correct Answer: ADE

QUESTION 4

Leads4Pass

https://www.leads4pass.com/hp2-t23.html 2024 Latest leads4pass HP2-T23 PDF and VCE dumps Download

Which hardware-based system security feature can securely store information such as passwords and encryption keys
and can be used to authenticate the platform?

- A. DHCP
- B. RBSU
- C. ORCA
- D. TPM

Correct Answer: D

QUESTION 5

Which step must be performed after the system board is replaced on a ProLiant BL460c G8 server blade?

- A. Enable ASR.
- B. Re-enter the serial number.
- C. Clear the NVRAM.
- D. Reconfigure the array.

Correct Answer: B

Latest HP2-T23 Dumps

HP2-T23 PDF Dumps HP2-T23 Exam Questions